

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin

NA0005	Overall LMA Rating	Total LMA Miles				
City of Sacramento	A	3.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Vegetation	0.01		0.01	0.28%		
Encroachments					0.80	
<i>LMA Totals:</i>	0.01	0.00	0.01	0.28%	0.80	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2008 Levee Inspection Results

City of Sacramento

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2008 Levee Inspection Results

City of Sacramento

Waterway			Bank	Unit Miles
Unit No. 01 City of Sacramento			Left	3.60
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/5/2008		9/22/2008	
DWR Inspector	John Williamson		John Williamson	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

City of Sacramento

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 City of Sacramento							Left	3.60	09/22/2008	John Williamson	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.14	0.14	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: state recorder can(DWR) fenced area	38.588715 ° -121.504885 °	38.588715 ° -121.504885 °	Y	1
2	0.16	0.16	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: historical building	38.588425 ° -121.504860 °	38.588425 ° -121.504860 °	Y	2
3	0.31	1.15	Concrete Floodwalls	Concrete Surfaces	WS	A	Inspector Comments: Flood wall starts at 1st bridge and runs downstream thru Old Sacramento past Embassy Suites down Front St. LM 1.13. Levee is oversize on crown with railroad tracks and structures.	38.586418 ° -121.505195 °	38.574880 ° -121.510098 °	Y	3
4	0.78	0.78	Earthen Levee	Encroachments	CR	PO	Buildings Inspector Comments: Embassy Suites	38.579712 ° -121.507347 °	38.579712 ° -121.507347 °	Y	4
5	0.78	0.93	Earthen Levee	Encroachments	CR	PO	Landscaping Inspector Comments: River walk along the water front	38.579705 ° -121.507360 °	38.577740 ° -121.508147 °	Y	5
6	1.73	1.96	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: Levee is oversize with railroad tracks and paved parking this area is Miller Park	38.568172 ° -121.516042 °	38.564882 ° -121.516265 °	Y	6
7	1.96	2.34	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: Railroad tracks run on crown of levee, paved roadway runs along toe on waterside this is Miller Park Marina area.	38.564900 ° -121.516253 °	38.559460 ° -121.515085 °	Y	7
8	2.45	2.45	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.557937 ° -121.514237 °	38.557937 ° -121.514237 °		8
9	2.90	2.90	Earthen Levee	Encroachments	CR	PO	Buildings	38.551810 ° -121.511838 °	38.551810 ° -121.511838 °	Y	10

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 City of Sacramento	Left	3.60	09/22/2008	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.14
End Levee Mile	0.14
Location	
Category	Earthen Levee
Item	Encroachments
Recorder can (DWR)	



Levee Mile Report Line	2
Start Levee Mile	0.16
End Levee Mile	0.16
Location	
Category	Earthen Levee
Item	Encroachments
Historical Building : State Parks & Recreations	



Levee Mile Report Line	3
Start Levee Mile	0.31
End Levee Mile	1.15
Location	
Category	Concrete Floodwalls
Item	Concrete Surfaces
Old Sacramento Flood wall	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 City of Sacramento	Left	3.60	09/22/2008	John Williamson

Levee Mile Report Line	3
Start Levee Mile	0.31
End Levee Mile	1.15
Location	
Category	Concrete Floodwalls
Item	Concrete Surfaces
Old Sacramento boardwalk flood wall below	



Levee Mile Report Line	4
Start Levee Mile	0.78
End Levee Mile	0.78
Location	
Category	Earthen Levee
Item	Encroachments
Embassy Suites	



Levee Mile Report Line	5
Start Levee Mile	0.78
End Levee Mile	0.93
Location	
Category	Earthen Levee
Item	Encroachments
River walk crown with landscaping	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

City of Sacramento

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 City of Sacramento	Left	3.60	09/22/2008	John Williamson

Levee Mile Report Line	6
Start Levee Mile	1.73
End Levee Mile	1.96
Location	
Category	Earthen Levee
Item	Encroachments
Miller Park at Broadway rail road track and parking area on levee	



Levee Mile Report Line	7
Start Levee Mile	1.96
End Levee Mile	2.34
Location	
Category	Earthen Levee
Item	Encroachments
Rail road tracks on levee crown street to boat ramp	



Levee Mile Report Line	9
Start Levee Mile	2.90
End Levee Mile	2.90
Location	
Category	Earthen Levee
Item	Encroachments
pump station city of Sacramento crown of levee waterside	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected